

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON		API Number 30-025-25996	
Property Name CENTRAL VACUUM UNIT		Well No. 135	

Surface Location

Blk. - Lot L	Section 6	Township 18S	Range 3SE	-	Feet from 1600	N/S Line FSL	Feet From 40	E/W Line FWL	County LEA
------------------------	---------------------	------------------------	---------------------	----------	--------------------------	------------------------	------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD -	OIL -	PRODUCER -	GAS -	DATE 5/5/14
------------------	----	----------------	----	------------------------	-----------------	-----------------	----------------------	-----------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0	170	1800
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 -
Steady Flow	Y / N	Y / N	Y / N	N / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS -
Down to nothing	Y / N	Y / N	Y / N	N / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	N / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

D Packer fluid bled down to zero. Verified 24 hours later that pressure was still at zero.

FOR RECORD ONLY

BS 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McWen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/14/14	Phone: 575-942-3526		
Witness:			

JUL 30 2014

