

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 23 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <i>Mesquite SWD Inc</i>		API Number <i>30-025-27616</i>	
Property Name <i>Paduca Federal SWD</i>		Well No. <i>1</i>	

7. Surface Location

UL - Lot <i>H</i>	Section <i>22</i>	Township <i>25S</i>	Range <i>32E</i>	Feet from <i>1980'</i>	N/S Line <i>N</i>	Feet From <i>660</i>	E/W Line <i>E</i>	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	---------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJ INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE <i>7-17-2014</i>
--	--	---	---	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					<i>280</i>
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	Y / N	☒ Y ☐ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 7/24/2014

Signature:		OIL CONSERVATION DIVISION	
Printed name: <i>Clay L Wilson</i>		Entered into RBDMS	
Title: <i>President</i>		Re-test	
E-mail Address: <i>claylwilson@hotmail.com</i>			
Date:	Phone: <i>575-706-1840</i>		
	Witness: <i>Bill Sonnamaker OCD</i>		

JUL 30 2014

[Signature]