

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON	API Number 30-025-30847
Property Name VACUUM GRAYBURG SAN ANDRES UNIT	Well No. 149

2. Surface Location

UL - Lot C	Section 1	Township 18S	Range 34E	Feet from 1330	N/S Line FNL	Feet from 1980	E/W Line FWL	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	GAS	DATE 5/5/14
------------------	---------------	------------------------	-----------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	25		150	1450
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 X
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.


(B) Small amount of gas bled down to zero.

(D) Dacker fluid bled down to zero.

Verified both pressure were still at zero 24 hours later.

FOR RECORD ONLY

BS 7/25/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McGuen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/14/14	Phone: 575 942-3526
Witness:	

JUL 30 2014