

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON						API Number 30-025-38555			
Property Name VACUUM GRAYBURG SAN ANDRES UNIT						Well No. 145			
7. Surface Location									
UL - Lot C	Section 2	Township 18S	Range 34E	✓	Feet from 1286	N/S Line FNL	Feet from 1831	E/W Line FWL	County LFA
Well Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR INJ ✓		PRODUCER OIL		DATE 5/5/14	

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			10	2075
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	0 / N	CO2 X
Steady Flow	Y / N	Y / N	Y / N	0 / N	WTR
Surges	Y / N	Y / N	Y / N	0 / N	GAS
Down to nothing	Y / N	Y / N	Y / N	0 / N	Type of fluid injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	0 / N	
Water	Y / N	Y / N	Y / N	0 / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Small amount of gas bled down to zero, verified pressure at zero 24 hours later.

FOR RECORD ONLY

BL 7/20/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McGuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: innb@chevron.com			
Date: 7/13/14	Phone: 575 942-3526		
Witness:			

JUL 30 2014

