

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 23 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Mesquite SWD Inc.		API Number 30-025-40813
Property Name Paduca Federal SWD		Well No. 2

2. Surface Location

UL Lot 0	Section 22	Township 25S	Range 32E	Feet from 500'	N/S Line S	Feet From 2,000	E/W Line E.	County Lea
-------------	---------------	-----------------	--------------	-------------------	---------------	--------------------	----------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE 7-17-2014
------------------	----------------	-----------------	-----------------	-----	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0	0	380
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

RECORD ONLY

BS 7/24/2014

Signature:		OIL CONSERVATION DIVISION
Printed name: Clay L. Wilson		Entered into RBDMS
Title: President		Re-test
E-mail Address: Clayl.wilson@hotmail.com		
Date:	Phone: 575-706-1840	
Witness: Bill Sonnemaker OCD		

JUL 30 2014

hfw