

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON					API Number 30-025-24378				
Property Name VACUUM GRAYBURG SAN ANDRES UNIT					Well No. 015				
Surface Location									
UL - Lot 5	Section 2	Township 18S	Range 34E	☒	Feet from 1400	N/S Line FSL	Feet From 2450	E/W Line FEL	County LEA
Well Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR ☒ INJ		PRODUCER OIL		DATE 5/5/14	

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0				0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is currently inactive for a well head failure

FOR RECORD ONLY

BS 7/25/2014

Signature: 		OIL CONSERVATION DIVISION
Printed name: Jane McCuen		Entered into RBDMS
Title: Sub Surface Production Specialist		Re-test
E-mail Address: lnnb@chevron.com		
Date: 7/10/14	Phone: 575 942-3526	
Witness:		

JUL 30 2014

