

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON		API Number 30-025-35562	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 235	

2. Surface Location

U/L - Lot H	Section 1	Township 18S	Range 34E	☒	Feet from 2610	N/S Line FNL	Feet from 660	E/W Line FEL	County LEA
-----------------------	---------------------	------------------------	---------------------	-------------------------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER	GAS	DATE 5/5/14
------------------	----	----------------	----	------------------------	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			190	1850
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 X
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) packer fluid, bled down to zero. Came back 24 hours later + verified pressure was still at zero.

FOR RECORD ONLY

BA 7/25/2014

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/14/14	Phone: 575 942-3526		
Witness:			

JUL 30 2014