

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON		API Number 30-025-25814	
Property Name CENTRAL VACUUM UNIT		Well No. 26	

Surface Location

U.L. - Lot 5	Section 25	Township 17S	Range 34E	Feet from 1330	N/S Line FSL	Feet From 2577	E/W Line FEL	County LEA
------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status


TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	SWD ✓	OIL ✓	PRODUCER GAS	DATE 5/5/14
------------------	---------------	------------------------	-----------------	-----------------	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			500	1200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) would not bleed down, **Failure**
> Letter of Violation "For Record Only" **FOR RECORD ONLY**
NOT CIO3. do repair well approved 7/17/14, OAD/OCD 7/30/14
BS 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McQueen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/14/14	Phone: 575-942-3526		
Witness:			

JUL 31 2014

