

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-31700	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 39	

7. Surface Location

U/L - Lot M	Section 25	Township 17S	Range 34E	☒	Feet from 1194	N/S Line FSL	Feet From 1055	E/W Line FWL	County LEA
-----------------------	----------------------	------------------------	---------------------	-------------------------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	☒ INJ	SWD	OIL	PRODUCER GAS	DATE 5-2-14
------------------	----	----------------	----	---	-----	-----	-----------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			85	575
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / ☒ N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	☒ Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / ☒ N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒ N	Injected for
Water	Y / N	Y / N	Y / N	☒ Y / N	Waterflow if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) packer fluid bled down to zero. Checked 24 hours later, pressure was still at zero.

FOR RECORD ONLY

BS 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@cherron.com			
Date: 7/14/14	Phone: 575-942-3526		
Witness:			

JUL 31 2014/

