

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-31838	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 41	

Surface Location

U/Lot 5	Section 25	Township 17S	Range 34E	Feet from 1377	N/S Line FSL	Feet From 1646	E/W Line FEL	County LEA
-------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 5-5-14
------------------	----------------	------------------------	-----------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csgng	(E)Tubing
Pressure	0			25	30
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	(Y) N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / (N)	WTR X
Surges	Y / N	Y / N	Y / N	Y / (N)	GAS —
Down to nothing	Y / N	Y / N	Y / N	(Y) / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / (N)	Injected for
Water	Y / N	Y / N	Y / N	(Y) / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) packer fluid bled down to zero, verified 24 hours later that pressure was still at zero.

FOR RECORD ONLY

BS 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/14/14	Phone: 575-942-3526		
Witness:			

JUL 31 2014