

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 3002532772
1. Type of Well: Oil Well ☐ Gas Well ☒ Other Injector ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CHEVRON U.S.A. INC		6. State Oil & Gas Lease No.
3. Address of Operator 15 SMITH ROAD MIDLAND, TX 79705		7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
4. Well Location Unit Letter B -: 640 feet from the NORTH line and 2000 feet from the EAST line Section 5 Township 25-S Range 38-E NMPM County LEA		8. Well Number 151
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 432
		10. Pool name or Wildcat DOLLARHIDE TUBB DRINKARD

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ANNUAL MIT TEST

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

CHEVRON U.S.A. INC HAS CONDUCTED THE ANNUAL MIT TEST ON THE ABOVE WELL.
CHART ATTACHED.

****PLEASE NOTE THIS TEST IS FOR UIC ANNUAL TESTING****

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Adriann Garcia TITLE REGULATORY ASSISTANT DATE 7/24/14


Type or print name **Adriann Garcia** E-mail address: **Adriann.Garcia@chevron.com** PHONE: **432-687-7617**

For State Use Only

APPROVED BY: Bill Lewman TITLE State Manager DATE 8/1/2014

Conditions of Approval (if any):

AUG 04 2014



BR 8/1/2014

FOR RECORD ONLY

JUL 30 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherron	API Number 3002532772
Property Name Dollarhide	Well No. WDDU 151

Surface Location

UL - Lot	Section E038	Township 5	Range 5425	Feet from	N/S Line	Feet From	E/W Line	County LEA
----------	------------------------	----------------------	----------------------	-----------	----------	-----------	----------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 5/13/14
-------------	----------------	-----------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	0	0	0	0
Flow Characteristics					
Puff	Y / 0	Y / 0	Y / 0	Y / 0	Y / 0
Steady Flow	Y / 0	Y / 0	Y / 0	Y / 0	Y / 0
Surges	Y / 0	Y / 0	Y / 0	Y / 0	Y / 0
Down to nothing	Y / 0	Y / 0	Y / 0	Y / 0	Y / 0
Gas or Oil	Y / 0	Y / 0	Y / 0	Y / 0	Y / 0
Water	Y / 0	Y / 0	Y / 0	Y / 0	Y / 0

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

TA'D

FOR RECORD ONLY

BS 8/1/2014

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Luke Robertson	Entered into RBDMS
Title: Field specialist	Re-test
E-mail Address: lra@cherron.com	
Date: 6/4/14	
Phone: (432) 266-2806	
Witness:	

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name chevron		API Number 3002532772	
Property Name Dollarhide		Well No. WDDU 151	

7. Surface Location

UL - Lot	Section 5	Township S024	Range E038	Feet from 640	N/S Line N	Feet From 2000	E/W Line E	County Lca
----------	---------------------	-------------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 7/10/14
---	----	----------------	----	-----	-----------------	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Water Cond if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/1/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Luke Robertson		Entered into RBDMS	
Title: Field Specialist		Re-test	
E-mail Address: lrak@chevron.com			
Date: 7/10/14	Phone: 432 266 2806		
Witness: Bill Songmaker			

