

AUG 06 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON		API Number 30-025-02202-	
Property Name WEST VACUUM UNIT		Well No. 028 -	

Surface Location

UL - Lot 3	Section 34	Township 17S	Range 34E	Feet from 1980	N/S Line F&L	Feet From 1980	E/W Line F&L	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------------	--------------------------	----------------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	DATE 7/10/14
------------------	---------------	-----------------	------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Cspg	(E)Tubing
Pressure	0			0	5
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Currently down for wellhead repair

FOR RECORD ONLY

BS 8/11/2014

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: Dane McWen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/30/14	Phone: 575-942-3526		
Witness:		[Signature]	

AUG 12 2014