

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 08 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON		API Number 30779	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 72 Y -	

2. Surface Location

Bl. - Lot D	Section 1	Township 18S	Range 34E	Feet from 1330	N/S Line FWL	Feet From 660	E/W Line FWL	County LEA
-----------------------	---------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status **2008 / N + 990 / W**

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 5/5/14
------------------	----	----------------	----	------------	------------	------------------------	------------	-----------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	680		15	30
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(B) Gas pressure blew down to zero in ten minutes, Verified 24 hrs later pressure was still at zero

FOR RECORD ONLY

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McEwen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lmb@chevron.com			
Date: 7/23/14	Phone: 575-942-3526		
Witness:			

AUG 12 2014