

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-33587
Property Name WEST VACUUM UNIT	Well No. 056

Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
0	34	17S	34E	✓	100	FSL	2450	FEL	LEA

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ	SWD	OIL	GAS	7/10/14

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			0	✓
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

No tubing in well.

FOR RECORD ONLY

BS 8/11/2014

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Dane McQueen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lnmb@chevron.com	
Date: 7/30/14	Phone: 575-942-3526
Witness:	

AUG 12 2014