

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

HOBBS OCD

AUG 01 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.		API Number 30-025-32915 ✓	
Property Name East Corbin Delaware Unit		Well No. 9 ✓	

Surface Location

UL - Lot	Section 21	Township 18S	Range 33E	✓	Feet from 1340	N/S Line North	Feet from 990	E/W Line East	County Lea
----------	---------------	-----------------	--------------	---	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Active	PRODUCING Injecting ✓	DATE 7/7/14
-------------	-------------------	--------------------------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			0	950
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:


(A) Opened valve, no pressure
(D) Opened valve, no pressure

FOR RECORD ONLY

Well active during test.

Field information submitted by Candy Aguilar

BS 8/8/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Stan Wagner		Entered into RBDMS	
Title: Regulatory Analyst		Re-test	
E-mail Address: stan.wagner@eogresources.com			
Date: 7/28/2014	Phone: 432-686-3689		
Witness:			

AUG 12 2014