

AUG 08 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-06896
Property Name Central Drinkard Unit	Well No. 107

1. Surface Location

UL - Lot G	Section 29	Township 21S	Range 37E	☒	Feet from 1980	N/S Line FNL	Feet from 1980	E/W Line FEL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING Injector	DATE 5/26/14
-------------------------	---------	------------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Intern	(B)Intern(1)-Intern(2)	(C)Intern-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	0		0	2100
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

FOR RECORD ONLY

B8 8/11/2014

Signature: Justin Hobbs	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: KUV@chevron.com	
Date: 5/26/14	
Phone: 575-631-4228	
Witness:	

AUG 13 2014