

HOBBS OCD

AUG 08 2014

District 1
1625 N. Peach Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0726

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-06929
Property Name Central Drunkard Unit	Well No. 137

7. Surface Location

UL - Cat E	Section 32	Township 21S	Range 37E	☒	Feet from 1980	N S Line FNL	Feet from 810	E/W Line FNL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING Injector	DATE 5/25/14	☒
-------------------------	---------	------------------------------	------------------------	-------------------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	0		0	1300
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

FOR RECORD ONLY

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: KUW@chevron.com	
Date: 5/25/14	Phone: 575-631-4228
Witness:	

AUG 13 2014