

AUG 08 2014

District I
1625 N. Orchard Dr., Hobbs, NM 88249
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025 10434 OK
Property Name Ollie J Boyd	Well No. 2

2. Surface Location

UL - Lot D	Section 23	Township 22S	Range 37E	☒	Feet from 330	N.S. Line FNL	Feet from 440	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------------------	-------------------------	-------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING Pumping ☒	DATE 5/2/2014
-------------------------	---------	---	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Intern	(B)Intern(1)-Intern(2)	(C)Intern-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	0		30	30
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

FOR RECORD ONLY

BS 8/11/2014

Signature: J Hobbs	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: KUVV@chevron.com	
Date: 5/2/2014	Phone: 575-631-4228
Witness:	

AUG 13 2014