

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 08 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-20753	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 116	

Surface Location

UL - Lot D	Section 6	Township 18S	Range 35E	Feet from 330	N/S Line FNL	Feet From 560	E/W Line FNL	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	DATE 5/5/14
------------------	---------------	-----------------	------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			30	70
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/11/2014

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/24/14	Phone: 575-942-3526		
Witness:			

AUG 13 2014