

AUG 08 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-20754
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 117

Surface Location

UL - Lot C	Section 6	Township 18S	Range 35E	✓	Feet from 330	N/S Line FWL	Feet From 1571	E/W Line FWL	County LEA
----------------------	---------------------	------------------------	---------------------	----------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL ✓	GAS	DATE 5/5/14
------------------	----	----------------	----	-----	-----------------	--------------------------	-----	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	20			30	40
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Small amount of packer fluid, bled down instantly

FOR RECORD ONLY

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McEwen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/24/14	
Phone: 575-942-3526	
Witness:	

AUG 13 2014

