

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 08 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON		API Number 30-025-31129	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 118	

Surface Location

U/L - Lot B	Section 6	Township 18S	Range 36E	Feet from ✓	N/S Line FNL	Feet From 2135	E/W Line FEL	County LEA
-----------------------	---------------------	------------------------	---------------------	-----------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL	GAS	DATE 5/5/14
------------------	----	----------------	----	------------	------------	------------------------	-----	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	50		30	110
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	0 / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / 0	Y / N	Y / N	GAS ___
Down to nothing	Y / N	0 / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	0 / N	Y / N	Y / N	Injected for
Water	Y / N	Y / 0	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(B) Gas pressure bled down to zero. Verified 24 hours later that pressure was still at zero.

FOR RECORD ONLY

BS 8/11/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/24/14	Phone: 575-942-3526		
Witness:			

AUG 13 2014