

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-03101 ✓
Property Name STATE AN	Well No. 001 ✓

Surface Location

UL - Lot A	Section 7	Township 18S	Range 35E ✓	Feet from 330	NS Line FNL	Feet From 990	E/W Line FEL	County LEA
----------------------	---------------------	------------------------	-----------------------	-------------------------	-----------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 5/5/14
------------------	----	----------------	----	------------	------------	------------------------	------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	140		40	300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ---
Steady Flow	Y / N	0 / N	Y / N	Y / N	WTR ---
Surges	Y / N	Y / N	Y / N	Y / N	GAS ---
Down to nothing	Y / N	0 / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	0 / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(B) Gas pressure took about 18 minutes to bleed down to zero. Verified 24 hours later pressure was still at zero

FOR RECORD ONLY

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McQueen	Entered into RDBMS
Title: Production Specialist	Re-test
E-mail Address: lennb@chevron.com	
Date: 7/29/14	Phone: 575-942-3526
Witness:	

AUG 13 2014