

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-24019
Property Name NORTH VACUUM ABO WEST UNIT		Well No. 011

Surface Location

U/L - Lot D	Section 21	Township 17S	Range 34E	Feet from ✓ 660	N/S Line FSL	Feet From 660	E/W Line FEL	County LEA
-----------------------	----------------------	------------------------	---------------------	---------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL ✓	GAS GAS	DATE 7/10/14
------------------	----	----------------	----	------------	------------	--------------------------	------------	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McWen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lmb@chevron.com	
Date: 7/30/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

