

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-24061	
Property Name NORTH VACUUM ABO WEST UNIT		Well No. 008	

2. Surface Location

U/L - Lot 5	Section 21	Township 17S	Range 34E	✓	Feet from 2120	N/S Line FSL	Feet From 1840	E/W Line FEL	County LEA
-----------------------	----------------------	------------------------	---------------------	----------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 6/20/14
------------------	----	----------------	----	-----	-----------------	------------------------	-----	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		50	150
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

B8 8/11/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McWen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lmb@chevron.com			
Date: 7/30/14	Phone: 575-942-3526		
Witness:			

AUG 13 2014

h