

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON					API Number 30-025-24062				
Property Name NORTH VACUUM ABO WEST UNIT					Well No. 010				
Surface Location									
UL - Lot N	Section 21	Township 17S	Range 34E	☒	Feet from 660	N/S Line FSL	Feet From 2180	E/W Line Ful	County LEA
Well Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR INJ		PRODUCER OIL		DATE 7/10/14	


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			38	200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/11/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McWen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/30/14	Phone: 575-942-3526		
Witness:			

AUG 13 2014