

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON	API Number 30-025-33638
Property Name NORTH VACUUM ABO WEST UNIT	Well No. 027

Surface Location

U/L - Lot K	Section 27	Township 17S	Range 34E	Feet from 2080	N/S Line FSL	Feet From 2080	E/W Line FWL	County LEA
-----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 7/10/14
------------------	----	----------------	----	-----	-----------------	------------------------	-----	------------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			30	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Currently down for rod string failure

FOR RECORD ONLY

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McQueen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lmb@cheuron.com	
Date: 7/30/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

