

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	API Number 30-025-38140 ✓
Property Name NEW MEXICO O STATE NG-1	Well No. 040 ✓

Surface Location

BL - Lot 3	Section 36	Township 17S	Range 34E	✓	Feet from 1885	N/S Line FSL	Feet From 1978	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	---	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 6/14/14
------------------	----	----------------	----	-----	-----------------	------------------------	-----	------------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	120			50	25
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) gas pressure blew down in about 10 minutes.
Verified 24 hours later that pressure was still zero.

FOR RECORD ONLY

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McWen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lmm@chevron.com	
Date: 7/29/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

