

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON						API Number 30-025-02245			
Property Name VACUUM GRAYBURG SAN ANDRES UNIT						Well No. 042			
Surface Location									
UL - Lot G	Section 1	Township 18S	Range 34E	✓	Feet from 1980	N/S Line FNL	Feet From 1980	E/W Line FEL	County LEA
Well Status									
TA'D WELL YES		SHUT-IN NO		INJ NO		PRODUCER OIL ✓		DATE 5/5/14	

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	4		110	410
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(B) Small amount of gas pressure blew down instantly

FOR RECORD ONLY

B8 8/11/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/23/14	Phone: 575 942-3526		
Witness:			

AUG 13 2014