

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	API Number 30-025-02251
Property Name VACUUM GRAYBURG SAN ANDRES UNIT	Well No. 056

Surface Location

UL - Lot C	Section 1	Township 18S	Range 34E	☒	Feet from 671	N/S Line FNL	Feet From 1980	E/W Line FWL	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status


TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	INJECTOR SWD	OIL OIL	PRODUCER GAS	DATE 5/5/14
------------------	----	----------------	----	------------	-----------------	------------	------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	5			5	400
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Small amount of gas bled down instantly
(B) Small amount of gas bled down instantly
Verified Both Strings were still at zero 24 hours later
BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McCuen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lmbb@chevron.com	
Date: 7/23/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

