

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-02266	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 051	

Surface Location									
UL Lot D	Section 2	Township 18S	Range 34E	✓	Feet from 660	N/S Line FNL	Feet From 660	E/W Line FWL	County LEA

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 5/5/14
------------------	----	----------------	----	------------	------------	------------------------	------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			35	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/11/2014

Signature: Dane McCuen		OIL CONSERVATION DIVISION
Printed name: Dane McCuen		Entered into RBDMS
Title: Sub Surface Production Specialist		Re-test
E-mail Address: lnnb@chevron.com		
Date: 7/23/14	Phone: 575 942-3526	
Witness:		

AUG 13 2014