

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON						API Number 30-025-30755			
Property Name VACUUM GRAYBURG SAN ANDRES UNIT						Well No. 139 -			
Surface Location									
UL - Lot H	Section 2	Township 18S	Range 34E	✓	Feet from 1980	N/S Line FNL	Feet From 1282	E/W Line FEL	County LEA
Well Status									
TA'D WELL YES NO		SHUT-IN YES NO		INJECTOR INJ SWD		PRODUCER OIL GAS		DATE 5/5/14	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			30	100
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Waterflood if
Water	Y / N	Y / N	Y / N	Y / N	applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/11/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McGuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/23/14	Phone: 575 942-3526		
Witness:			

AUG 13 2014

