

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON		API Number 30-025-30756	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 140	

Surface Location

UL - Lot H	Section 2	Township 18S	Range 34E	✓	Feet from 1980	N/S Line FNL	Feet From 10	E/W Line FEL	County LEA
----------------------	---------------------	------------------------	---------------------	----------	--------------------------	------------------------	------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	OIL ✓	PRODUCER GAS	DATE 5/5/14
------------------	----	----------------	----	-----	-----------------	---------------------	-----------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			100	100
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Currently down for a hole in the tubing awaiting rig work.

Failure

BS 8/11/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 5/5/14	Phone: 575 942-3526		
Witness:			

AUG 13 2014

