

JUL 31 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-30797	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 141 -	

Surface Location

UL - Lot E	Section 1	Township 18S	Range 34E	Feet from 1980	N/S Line FSL	Feet from 1309	E/W Line FUL	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 5/5/14
------------------	----	----------------	----	------------	-----------------	------------------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	6			150	360
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Small amount of gas blew down to zero instantly

FOR RECORD ONLY

BS 8/11/2014

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: Dane McGuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/23/14	Phone: 575 942-3526		
Witness:			

AUG 13 2014

[Signature]