

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

|                                                         |  |                                   |  |
|---------------------------------------------------------|--|-----------------------------------|--|
| Operator Name<br><b>CHEURON</b>                         |  | API Number<br><b>30-025-31993</b> |  |
| Property Name<br><b>VACUUM GRAYBURG SAN ANDRES UNIT</b> |  | Well No.<br><b>227 -</b>          |  |

Surface Location

|                      |                     |                        |                     |   |                          |                        |                          |                        |                      |
|----------------------|---------------------|------------------------|---------------------|---|--------------------------|------------------------|--------------------------|------------------------|----------------------|
| UL - Lot<br><b>5</b> | Section<br><b>1</b> | Township<br><b>18S</b> | Range<br><b>34E</b> | - | Feet from<br><b>1980</b> | N/S Line<br><b>FSL</b> | Feet From<br><b>1755</b> | E/W Line<br><b>FEL</b> | County<br><b>LEA</b> |
|----------------------|---------------------|------------------------|---------------------|---|--------------------------|------------------------|--------------------------|------------------------|----------------------|

Well Status

|                  |    |                |    |     |                 |                          |     |                       |
|------------------|----|----------------|----|-----|-----------------|--------------------------|-----|-----------------------|
| TA'D WELL<br>YES | NO | SHUT-IN<br>YES | NO | INJ | INJECTOR<br>SWD | PRODUCER<br><b>OIL</b> - | GAS | DATE<br><b>5/5/14</b> |
|------------------|----|----------------|----|-----|-----------------|--------------------------|-----|-----------------------|

OBSERVED DATA


|                      | (A)Surface   | (B)Interm(1) | (C)Interm(2) | (D)Prod Casing | (E)Tubing                                                 |
|----------------------|--------------|--------------|--------------|----------------|-----------------------------------------------------------|
| Pressure             | <b>25</b>    |              |              | <b>25</b>      | <b>30</b>                                                 |
| Flow Characteristics |              |              |              |                |                                                           |
| Puff                 | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | CO2 ___                                                   |
| Steady Flow          | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | WTR ___                                                   |
| Surges               | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | GAS ___                                                   |
| Down to nothing      | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | Type of Fluid<br>Injected for<br>Waterflood if<br>applies |
| Gas or Oil           | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   |                                                           |
| Water                | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   |                                                           |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Gas blew down to zero in less than a minute.  
Verified 24 hrs later that pressure was still at zero.

FOR RECORD ONLY

BS 8/11/2014

|                                                                                                |                            |                           |  |
|------------------------------------------------------------------------------------------------|----------------------------|---------------------------|--|
| Signature:  |                            | OIL CONSERVATION DIVISION |  |
| Printed name: <b>Dane McGuen</b>                                                               |                            | Entered into RBDMS        |  |
| Title: <b>Sub Surface Production Specialist</b>                                                |                            | Re-test                   |  |
| E-mail Address: <b>lnnb@chevron.com</b>                                                        |                            |                           |  |
| Date: <b>7/23/14</b>                                                                           | Phone: <b>575 942-3526</b> |                           |  |
| Witness:                                                                                       |                            |                           |  |

AUG 13 2014

