

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-33979
Property Name HOOVER 28	Well No. 004

Surface Location

UL - Lot I	Section 28	Township 17S	Range 35E	✓	Feet from 1650	N/S Line FSL	Feet From 330	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	----------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES ✓ NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL ✓ GAS	DATE 7/10/14
------------------------------	-------------------	---------------------	-------------------------------------	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csing	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

DOWN FOR REPAIRS

B8 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McWen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/30/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

