

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON	API Number 30-025-38628
Property Name VACUUM GRAYBURG SAN ANDRES UNIT	Well No. 228

Surface Location									
UL - Lot I	Section 1	Township 19S	Range 34E	✓	Feet from 2180	N/S Line FSL	Feet From GAO	E/W Line FEL	County LEA

Well Status								
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD	PRODUCER OIL	GAS	DATE 5/5/14

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	218	0		130	340
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N Gas	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) bled down to zero instantly. Checked 24 hours later pressure was back at 200psi. blew down to zero instantly

FOR RECORD ONLY

BS 8-11-2014

Signature: Dane McCuen	OIL CONSERVATION DIVISION
Printed name: Dane McCuen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/23/14	Phone: 575 942-3526
Witness:	

AUG 13 2014

h