

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON						API Number 30-025-38783			
Property Name VACUUM GRAYBURG SAN ANDRES UNIT						Well No. 405			
Surface Location									
UL - Lot H	Section 1	Township 18S	Range 34E	-	Feet from 1910	N/S Line FNL	Feet from 40	E/W Line FEL	County LEA
Well Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR INJ		PRODUCER OIL		DATE 5/5/14	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	10	40		170	240
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	N / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Small amount of gas blew down to zero instantly.
(B) Gas blew down to zero in less than a minute.
Verified both strings were still at zero 24 hours later.

FOR RECORD ONLY

138 8/11/2014

Signature: Dane McCuen		OIL CONSERVATION DIVISION
Printed name: Dane McCuen		Entered into RBDMS
Title: Sub Surface Production Specialist		Re-test
E-mail Address: lnnb@chevron.com		
Date: 7/23/14	Phone: 575 942-3526	
Witness:		

AUG 13 2014

L