

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-30103
Property Name CENTRAL VACUUM UNIT	Well No. 253

Surface Location

UL - Lot C	Section 36	Township 17S	Range 34E	Feet from 675	N/S Line FNL	Feet From 1330	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	☒ OIL	PRODUCER GAS	DATE 5/5/14
------------------	----	----------------	----	-----	-----------------	--------------------------------------	-----------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	25	25		180	450
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / N	CO2 ☐
Steady Flow	☒ Y / N	☒ Y / N	Y / N	Y / N	WTR ☐
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / N	GAS ☐
Down to nothing	☒ Y / N	☒ Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	☒ Y / N	☒ Y / N	Y / N	Y / N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) took 10 minutes to blow down to zero.
(B) took 5 minutes to blow down to zero.
Verified 24 hours later that both A + B were still at zero.

FOR RECORD ONLY

BS 8/08/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McQueen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/23/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

