

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON						API Number 30-025-30968			
Property Name VACUUM GLORIETTA WEST UNIT						Well No. 74			
Surface Location									
BL - Lot G	Section 36	Township 17S	Range 34E	-	Feet from 2310	N/S Line ENL	Feet From 1900	E/W Line FEL	County LEA
Well Status									
TA'D WELL YES		NO		SHUT-IN YES		NO		INJ INJECTOR	
								SWD	
								PRODUCER OIL	
								GAS	
								DATE 5/5/14	

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	10	40		50	200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A)+(B) Gas bled down quickly. Verified 24 hours later that pressure was still at zero.

FOR RECORD ONLY

B8 8/08/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/22/14	Phone: 575-942-3526		
Witness:			

AUG 13 2014