

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	API Number 30-025-33148
Property Name CENTRAL VACUUM UNIT	Well No. 277

Surface Location

UL - Lot I	Section 36	Township 17S	Range 34E	Feet from 2085	N/S Line FSL	Feet From 710	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 5/5/14
------------------	----	----------------	----	------------	------------	------------------------	------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	75	50		150	200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	N / N	N / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	N / N	N / N	Y / N	Y / N	Type of Fluid
Gas or Oil	N / N	N / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies


Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) took 12 minutes to blow down to zero.

(B) took 2 minutes to blow down to zero.

Verified both strings were still at zero 24 hours later.

RS 8/08/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane Mc Cuen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lmb@chevron.com	
Date: 7/23/14	
Phone: 575-942-3526	
Witness:	

AUG 13 2014

