

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 31 2014

BRADENHEAD TEST REPORT

Operator Name CHEURON	RECEIVED 30-025-02232
Property Name CENTRAL VACUUM UNIT	Well No. 54

Surface Location

U. - Lot D	Section 36	Township 17S	Range 34E	<input checked="" type="checkbox"/>	Feet from 660	N/S Line FNL	Feet from 660	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 5/5/14
------------------	----	----------------	----	-----------------	-----	------------------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C/sng	(E)Tubing
Pressure	350	0		180	200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) took four minutes for string to blow down to zero all gas. Came back 24 hours + string had 300 psia on it.

BS 8/08/2014

Signature:	OIL CONSERVATION DIVISION
Printed name: Dare McLean	Entered into RRDMS
Title: Production Specialist	Re-test
Email Address: lmb@chevron.com	
Date: 7/23/14	Phone: 575-942-3526
Witness:	

AUG 13 2014