

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON		API Number 30-025-70510	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 57	

Surface Location

U/L - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
A	35	17S	34E	✓	760	FNL	510	FEL	LEA

Well Status


TA'D WELL ☒ YES ☐ NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL ☒ GAS	DATE 5/5/14
--	-------------------	---------------------	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflow if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 8/8/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lmb@chevron.com			
Date: 7/22/14	Phone: 575-942-3526		
Witness:			

AUG 13 2014

