

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-30139
Property Name NEW MEXICO AB STATE	Well No. 009

Surface Location

U/L - Lot P	Section 6	Township 18S	Range 36E	☒	Feet from 538	N/S Line FSL	Feet From 818	E/W Line FEL	County LEA
-----------------------	---------------------	------------------------	---------------------	-------------------------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	INJECTOR SWD	PRODUCER OIL	GAS ☒	DATE 5/5/14
------------------	----	----------------	----	------------	-----------------	------------------------	--	-----------------------


OBSERVED DATA

	(A)Surface	(E)Interm(1)	(C)Interm(2)	(D)Prod Casing	(F)Tubing
Pressure	0	0	0	50	300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McQueen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lennb@chevron.com	
Date: 7/29/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

