

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON		API Number 30-025-33301	
Property Name NEW MEXICO L STATE		Well No. 18	

Surface Location									
UL - Lot A	Section 1	Township 18S	Range 34E	-	Feet from 810	N/S Line FWL	Feet From 650	E/W Line FEL	County LEA

Well Status								
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 5/5/14

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	160	210		25	350
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	N / N	N / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	N / N	N / N	Y / N	Y / N	Type of fluid injected for waterflood if applies.
Gas or Oil	N / N	N / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Gas blew down to zero in 30 seconds. Checked 24 hours later 10 psi, instantly blew down to zero.

(B) Gas blew down to zero in 2 minutes

FOR RECORD ONLY **AS 8/08/2014**

Signature: 	OIL CONSERVATION DIVISION
Printed name: Don McLean	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lmb@chevron.com	
Date: 6/25/14	Phone: 575-942-3526
Witness:	

AUG 13 2014

