

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	API Number 30-025-32028
Property Name VACUUM GRAYBURG SAN ANDRES UNIT	Well No. 128

Surface Location

UL - Lot I	Section 1	Township 18S	Range 34E	Feet from 1980	NS Line FSL	Feet from 1220	E/W Line FEL	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	-----------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 5/5/14
------------------	----	----------------	----	-----------------	-----	------------------------	-----	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	8			38	300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Gas blew down to zero in less than 30 seconds.
Verified 24 hours later pressure was still zero.

FOR RECORD ONLY

BS 8/08/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McWen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/23/14	Phone: 575-942-3526
Witness:	

AUG 14 2014

