

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 25 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-25798
Property Name CENTRAL VACUUM UNIT	Well No. 113

Surface Location

U/L - Lot L	Section 6	Township 18S	Range 35E	Feet from 1620	N/S Line FSL	Feet From 1100	E/W Line FWL	County LEA
-----------------------	---------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL PRODUCER GAS	DATE 7/14/14
------------------	----	-----------------------	----	------------------------	-----	---------------------	------------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		1400	250
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Down failure waiting on Rig ✓

FOR RECORD ONLY

B8 8/08/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McQueen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/21/14	Phone: 575-942-3526
Witness:	

AUG 18 2014

h. ju