

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-23916	
Property Name NORTH VACUUM ABO WEST UNIT		Well No. 022	

7. Surface Location

U.L. - Lot N	Section 27	Township 17S	Range 34E	☒	Feet from 760	N/S Line FSL	Feet From 1980	E/W Line FWL	County LEA
------------------------	----------------------	------------------------	---------------------	-------------------------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO		SHUT-IN ☐ YES ☐ NO		INJECTOR ☒ INJ ☐ SWD		PRODUCER ☐ OIL ☐ GAS		DATE 7/10/14	
--	--	---	--	--	--	---	--	------------------------	--

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	—
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

No tubing in well

FOR RECORD ONLY

BS 8/11/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McQueen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/30/14	Phone: 575-942-3526		
Witness:			

AUG 19 2014

