

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 06 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON	API Number 30-025-23917
Property Name NORTH VACUUM ABO WEST UNIT	Well No. 021

Surface Location

U/L - Lot P	Section 28	Township 17S	Range 34E	✓	Feet from 660	N/S Line FSL	Feet from 660	E/W Line FEL	County LEA
-----------------------	----------------------	------------------------	---------------------	---	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

YES ☒ NO ☐	YES ☐ NO ☐	YES ☒ NO ☐	SWD	OIL	GAS	DATE 7/10/14
---	--	---	-----	-----	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 8/11/2014

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Dane McWen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lmb@chevron.com	
Date: 7/30/14	Phone: 575-942-3526
Witness:	

AUG 19 2014

h