

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 25 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON		API Number 30-025-30798	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 147	

Surface Location									
U/L - Lot H	Section 2	Township 18S	Range 34E	☒	Feet from 1360	N/S Line FUL	Feet From 660	E/W Line FEL	County LEA

Well Status						DATE	
TA'D WELL YES	NO	SHUT-IN YES	NO	☒ INJ	SWD	OIL	GAS
							5/5/14

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			485	1890
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	☒ Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	☒ Y / N	WTR X
Surges	Y / N	Y / N	Y / N	☒ Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	☒ Y / N	Injected for
Water	Y / N	Y / N	Y / N	☒ Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Gas pressure bled down to zero, verified 24 hours later that pressure was still at zero **FOR RECORD ONLY**

BS 8/1/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/21/14	Phone: 575 942-3526		
Witness:			

AUG 19 2014

