

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 25 2014

BRADENHEAD TEST REPORT

Operator Name CHEVRON						RECEIVED 30-025-36681			
Property Name VACUUM GRAYBURG SAN ANDRES UNIT						Well No. 134			
Surface Location									
UL - Lot K	Section 1	Township 18S	Range 34E	Feet from ✓ 2630	NS Line FSL	Feet From 1980	E/W Line FWL	County LEA	
Well Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR INJ		PRODUCER OIL		DATE 5/5/14	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			300	1800
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 X
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Packer fluid bled down to zero, verified 24 hours later that pressure was still at zero.

BS 8/1/2014

Signature: Dane McCuen		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/2/14	Phone: 575 942-3526		
Witness:			

AUG 19 2014